

Designation: K1.H010/A11-E
Kind of contact operation: "A" not overlapping
Contact combination: "11" 1 NO + 1 NC
Type of mounting: "-E" for type of mounting E

Diagram illustrating the assembly of the KG20-100C terminal block:

- Insert the terminal block into the base unit.
- Connect the power supply wires (33, 34, 41, 42) to the terminal block.
- Connect the load wires to the terminal block.

The diagram also shows the ON/OFF switch operation, with the switch moving from the OFF position (0) to the ON position (1).